


Aircraft Parking / Docking Chart - EKBI

Billund



Changes : Displaced THR marking added, TWY centerlines added north of RWY. Refueling text withdrawn.

Apron South
Pavement : Concrete
Strength : PCN 110 / R / A / X / T

Note:
Permission to enter Apron South via intermediate holding position west of stand 1 must be obtained from Billund TWR, FREQ 129.505 MHZ.